

1924 Portland Tax Records: Doughty property, Long Island, Portland, 1924

Portland, Maine
Assessment 1924

Name *Doughty, Ella M.*
Owner *Long Island*
Street *101-B-4* No. *2-3*
Block *101-B-4* Lot
Use of Bldg. *Dwelling + Shed* Name
Tenants and Rooms *1-3 rooms + shed*
Rentals *owner*
Age *30+*
Condition of Repair *Fair*
(see back) *2093-A 2875*

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage <i>Barn</i> Foundation Brick Stone Concrete Pile Basement Full Cement Floor Waterproof Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough	Plumbing <i>no</i> Common Individual Open Set tubs Finish <i>no</i> Plain Com. Brick Hardwood Halls Wood Terra Cotta Marble Foot-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
---	---	---

Ground Area *2-6. Board* Height
Cubic Feet Unit cts.
Utility Dep.
Dep. Per cent.
Sound Value, \$
Land Corner Interior Alley
Front Depth = ft.
COMPUTATION
350-1931 325

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			



Surveyed by *Johnson & Casey*
2-3
(over)

*Barn divided into 4 rooms
3 used as rooms + 1 as shed
for storage*

not shown

2093-A 2875

Plumbing Common Individual Open Set tubs Finish Plain Com. Brick Hardwood Halls Wood Terra Cotta Marble Foot-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough	Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage <i>Barn</i> Foundation Brick Stone Concrete Pile Basement Full Cement Floor Waterproof Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame
---	---	---

Ground Area Height
Cubic Feet Unit cts.
Utility Dep.
Dep. Per cent.
Sound Value, \$
Land Corner Interior Alley
Front Depth = ft.
COMPUTATION
350-1931 325

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			

(over)

1924 Portland Tax Records: Doughty property, Long Island, Portland, 1924



Owner: Ella M. Doughty
Address: Long Island, Long Island, Portland, Maine
Use: Dwelling & Shed
Local Code: Block 101B Lot 4 Book 92 Page 2
MMN item number: 89110